U940170. Prop. 161736 C+JSIMMONDS BORE AT LONE GUN ESTATE DOG POINT RO Br.

B.

C

The original well put down by Mr O'Connell did fail and $J \cdot \& D \cdot Butt$ Welldriving were called in to rectify it It was decided to put down another we!J immediately along side the first well rather than attempt to fix the first one \cdot

Herewith are photograph of the 2 domestic wells numbered on the reverse :

"A" - which shows the first well which ha been capped off and abandoned · (The lateral in the photo goes past the structure and is nothing to do with the wel1). "B" - which shows the

replacement well head This has been set so it can be covered underground "C" - which show the 2 wells · They are about IO' apart We trust this is all of the information you require (C ·G ·R · Simmonds, Feb 1996)

Received 23/2/96 In





